

Message

From: Pidgeon, Bill [pidgeon.bill@epa.gov]
Sent: 4/3/2014 3:02:42 PM
To: Ball, Joel [ball.joel@epa.gov]
Subject: RE: 2007 Lexus IIS 250 exhaust leaks defect
Attachments: Lexus exhaust y-pipe 2014 0403.pdf

Joel,

For the following, no hits:

Mfr ID: Toyota/Lexus

MY: 2007

Problem: Defective/Incorrect Exhaust System

For the following, 28 hits – see attached:

Mfr ID: Toyota/Lexus

MY: no entry, which means All

Problem: Defective/Incorrect Exhaust System

Result: no MY2007s, does include a 2005.

Bill

William M. Pidgeon
Mechanical Engineer
U.S. Environmental Protection Agency
Compliance Division, N69
2000 Traverwood Drive
Ann Arbor, MI 48105-2195
pidgeon.bill@epa.gov
Phone: 734-214-4416
Fax: 734-214-4869

From: Ball, Joel
Sent: Thursday, April 03, 2014 9:40 AM
To: Pidgeon, Bill; Ott, William
Subject: 2007 Lexus IIS 250 exhaust leaks defect

Hi Bill,

Could you please look to see if there are any defect reports involving leaks in the exhaust y-pipe due to corrosion. I received a complaint on this that indicated that a Lexus dealer stated that this is a common problem.

Thanks

Joel Ball
Light-Duty Vehicle Group
Compliance Division
United States Environmental Protection Agency
(734) 214-4238
ball.joel@epa.gov